


# Fosera Scandle 200 Charging Terminal Replacement

In this guide instructions will be given on how to remove a charging terminal in the case that it stops working.

Written By: David




# INTRODUCTION

This guide will explain and show how to replace a charging terminal that has stopped working. Replacing it requires the use of a soldering iron and the Spudger. This is a fairly easy replacement guide and should only take around fifteen minutes.

## **TOOLS:**

- Phillips #0 Screwdriver (1)
- Spudger (1)
- Soldering Iron (1)

#### Step 1 — Motherboard Removal




 To open up the casing, you will need to unscrew the four Phillips #0
15mm screws which are accessible from the back.

## Step 2




• Gently separate the two halves of the casing.

#### Step 3




- Disconnect the battery from the motherboard by lifting up on the white plastic tab on the top of the connection.
- Gently pull the cord out by the white plastic adapter. Do not pull from the red and black cord.

#### Step 4




 Unscrew the Phillips four #0 15mm screws to free the motherboard from the casing.

#### Step 5




 Slowly pull the motherboard out of the casing. Make sure the loose battery wire doesn't get snagged.

#### Step 6 — Charging Terminal




- Use caution when using a soldering iron, the tip will be very hot.
  - Locate the charging terminal's three prong connectors on the back of the motherboard.

#### Step 7



 Start melting the solder on each prong connector individually with the soldering iron.

## Step 8



• Use the flat end of the spudger to pry the charging terminal away from the motherboard.

To reassemble your device, follow these instructions in reverse order.