Acer Chromebook 15 CB5-571-C09S Solid State Drive Replacement

Use this guide to replace the Solid State Drive or SSD in your Acer Chromebook 15 CB5-571-C09S.

Written By: Sakiynah Howard

www.iFixit.com

INTRODUCTION

This guide will walk you through replacing the SSD in your Acer Chromebook 15 CB5-571-C09S.

🔧 TOOLS:

- iFixit Opening Tools (1)
- Phillips #0 Screwdriver (1)
- Phillips #00 Screwdriver (1)

This document was generated on 2020-11-13 03:36:19 PM (MST).

www.iFixit.com

Step 1 — Back Cover

- Place the device on a flat surface faced down so that the fan vents are at the top of the device.

Step 2

- Unscrew the eighteen 6 mm PH0 Phillips head screws from the back of the device.

This document was generated on 2020-11-13 03:36:19 PM (MST).

Step 3

- Use a plastic opening tool to pry open the back cover around the edges of the device.

⚠️ Be careful not to crack or break the back cover of the device.

ⓘ You will have to adjust the position of the device to pry it open along all the edges.

Step 4

- Stand the device up with the hinges on top and carefully pull apart the back cover from the device.

Step 5 — Solid State Drive

ⓘ The Solid State Drive is the blue chip locate right beneath the fan.

● Unscrew the 3 mm PH00 Phillips head screw located on the left side of the SSD.

Step 6

● Grab the top and bottom edges of the SSD and carefully pull it out from the motherboard.

To reassemble your device, follow these instructions in reverse order.

|