Fix Receiver Internal Error / Error 4000 / No Model Info

Full solution on how to fix the Internal Error/Error 4000 and No Model Info messages on various Yamaha Receivers.

Written By: Nick Myers

This document was generated on 2022-03-21 01:31:53 AM (MST).

INTRODUCTION

Full solution on how to fix the Internal Error/Error 4000 and No Model Info messages on various Yamaha Receivers. This works with Yamaha RX-V673 and several other models.

Link to the current Yamaha firmware: https://europe.yamaha.com/en/support/upd...

This document was generated on 2022-03-21 01:31:53 AM (MST).

To reassemble your device, follow these instructions in reverse order.

This document was generated on 2022-03-21 01:31:53 AM (MST).