


## **Dell Inspiron 1525 Bottom Cover Replacement**

Written By: Miroslav Djuric



This document was generated on 2020-11-28 02:27:42 AM (MST).

## FOOLS:

• Phillips #1 Screwdriver (1)

This document was generated on 2020-11-28 02:27:42 AM (MST).

## Step 1 — Bottom Cover



- Remove/loosen the eight 4.80 mm Phillips #1 screws securing the bottom panel.
  - The screws may only need to be loosened, as they are generally retained by plastic washers.
- Remove the bottom panel.

To reassemble your device, follow these instructions in reverse order.

This document was generated on 2020-11-28 02:27:42 AM (MST).