



Hytera TC-580 Battery Replacement

Replace the battery of the Hytera TC-580 portable radio.

Written By: Stuart



INTRODUCTION

Remove (and replace) the battery of the TC-580. This is for radios that are having issues turning on or maintaining charge. This should be a simple fix without requiring too much time or complex tools.



TOOLS:

- [Phillips #0 Screwdriver](#) (1)
-

Step 1 — Battery



- Remove the two 10mm Phillips #0 from the belt clip.

Step 2



- Push in the release button and pull up on the battery to remove.

To reassemble your device, follow these instructions in reverse order.