

LCD LG 37LF65 Capacitor replacement

The TV turns off by itself after a while or the...

Written By: eugl18



INTRODUCTION

The TV turns off by itself after a while or the TV will not start, blown off capacitors could be the source off error.

TOOLS:

- Large Needle Nose Pliers (1)
- Soldering Workstation (1)

PARTS:

- 470uF 10V (2)
- 2200uF 10V (2)
- 3300uF 10V (2)
- 470uF 25V (1)
- 2200uF 25V (1)
- 470uF 35V (2)
- 680uF 35V (4)
- 1000uF 35V (1)

Step 1 — Open the case



Power off and unplug your device before starting this repair.

• Open the case carefully while loosing the marked srews.

Step 2 — Replace the capacitors



- Check the power-board. If there are any blown-up capacitors, you should replace them.
- For removing the capacitors, remove the board, take a soldering bolt and heat the solder points at the back of the board.
- Insert the replacement capacitors and solder it. Check the poles!

Step 3 — Testing capacitors



(i) If you are not sure about the condition of the capacitors you can prove it with a good measuring device after the expansion.

Not all capacitors are need in any case. To reassemble your device, follow these instructions in reverse order.