




# dreamGEAR Quad Dock Pro Electrical Port Replacement

Guide for replacing the electrical port of the dreamGEAR Quad Dock Pro.

Written By: Jacob



---

## INTRODUCTION

This is where all of the power comes into the device. Learn how to replace it. Be careful while soldering!

---

### TOOLS:

- [Phillips #0 Screwdriver](#) (1)
  - [Spudger](#) (1)
  - [Soldering Iron](#) (1)
  - [iFixit Opening Tools](#) (1)
-

## Step 1 — Prerequisite Guide to Accessing Interior




- Remove the rubber foot pads on the bottom of the device using a plastic opening tool.

## Step 2





- Remove the six 2 mm PH0 screws on the bottom of the device.
- ⓘ Four of those screws are located under the foot pads.

### Step 3




- Gently remove the bottom of the device.

### Step 4 — Mother Board




- Remove the four 1.8 mm J1 screws.
- Remove the two 2mm PH0 screws.

## Step 5




- Gently pick up the mother board
- ⚠ Pick the mother board straight up or you may risk damaging the mini-USB charging ports.

## Step 6



- Use a plastic opening tool or similar tool to gently pry the power ribbon cord out of its port.

## Step 7 — Electrical Port



- Locate the three solder connections for the electrical port.
  - Desolder the connection points following the instructions included with your soldering kit as you remove the port.
- ⚠ FIRE HAZARD! BURN DANGER!** Follow all the safety precautions included with your soldering kit.
- i** It is helpful to use a nylon or metal spudger or tweezers for the removal of this component, pieces of which are very hot.
  - i** You can follow iFixit's guide to soldering [here](#).

To reassemble your device, follow these instructions in reverse order.