

Rydis H68 Pro Battery Replacement

Battery running out fast? Follow this guide on...

Written By: Joe Balduz



INTRODUCTION

Battery running out fast? Follow this guide on how to change it for a new one.



TOOLS:

Tournevis cruciforme #1 (1)

Step 1 — Battery





- Flip the vacuum over so that the wheels are facing you.
- Use a Phillips #1 screwdriver to remove the four 10 mm screws that surround the battery cover.

Step 2



- Lift the battery cover up to reveal the battery.
- Remove the battery.

To reassemble your device, follow these instructions in reverse order.