

# Oregon Scientific RM318PA Battery Replacement

Replace Batteries to Fix a Clock which has Stopped Working

Written By: Maxine Holden



This document was generated on 2020-11-28 04:02:17 AM (MST).

# **INTRODUCTION**


Replacing the batteries may be a simple solution for a clock that has stopped functioning. Battery replacement can be completed in just a few steps.



# **PARTS:**

AA Batteries (2)

## **Step 1 — Battery Compartment**



 Locate the battery compartment cover on the back of the clock.

## **Step 2** — Removing Battery Compartment Cover



 To remove the battery compartment cover, slide the cover up towards the top of the clock while applying slight pressure.

## Step 3 — Batteries



 Using your fingertips and lifting up, take out the two AA batteries.

## **Step 4** — **Insert New Batteries**



 Once the old batteries are removed, insert new AA batteries.

To reassemble your device, follow these instructions in reverse order.